




A (x2)




B (x1)




C (x1)



D (x1)




E (x1)



F (x1)



G (x1)



H (x4)



I (x1)
M5x16



J (x1)
M10x20




K (x2)
M6x10



L (x2)



M (x2)
M3x8



N (x1)
4mm



O (x1)
6mm



M-A (x4)
M4x12




M-B (x4)
M5x12




M-C (x4)
D5

x2


1





2 Clamp Mounting





Grommet Mounting




























3















4



5

