



A (x2)




B (x2)




C (x1)



D (x2)



E (x1)



F (x1)



G (x1)



H (x1)



I (x2)
M6x8



J (x2)
M6x10



K (x2)
M8x30



L (x1)
4mm



M (x1)
5mm



M-A (x4)
M4x12




M-B (x4)
M5x12




M-C (x4)
D5

x2


1a




3a




2a







1b



4



5



6

