




A (x1)




B (x1)




C (x1)




D (x1)



E (x2)



F (x1)



G (x2)



H (x1)



I (x1)




J (x1)



K (x1)



L (x1)



M (x4)



N (x1)



O (x2)
M6x8



P (x4)
M6x12



Q (x4)
M6x16



R (x4)
M8x20



S (x4)
M8x30



T (x4)
M6x40



U (x1)
5mm



V (x1)
6mm




W (x1)
14-17mm




M-A (x4)
M6x14



M-B (x4)
M8x16



M-C (x4)
M6x30



M-D (x4)
M8x35



M-E (x4)
D8




M-F (x4)
Ø15xØ8x5




M-G (x4)
Ø15xØ8x15


1




2




3



4



5



6

